# Weld Joint Geometry and Welding Symbols

Basic Weld Joints
Welding Technology
LEE CO. ATC

**Graphics compliments of AWS** 




To the AWS Welding Educator's Electronic File Library www.aws.org/Educators

Graphics provided compliments of the American Welding Society Education Department


#### Five Basic Welded Joints


#### **Butt Joint**


Butt joint- a joint between two members aligned approximately in the same plane



# Different Edge Shapes and Symbols for some Butt-Joints









#### **Five Basic Welded Joints**

#### **Corner Joint**



Corner joint - a joint between two members located at right angles to each other


# Some Different Edge Shapes and Symbols for Corner Joints




### Five Basic Welded Joints

#### **T-Joint**

T- joint - a joint between two members located approximately at right angles to each other in the form of a T




## Some Different Edge Shapes and Symbols for T-Joint




### Five Basic Welded Joints


#### **Lap Joint**




Lap Joint- a joint between two overlapping members

# Some Different Edge Shapes and Symbols for Lap Joints









### Five Basic Welded Joints

#### **Edge Joint**

Edge joint- a joint between the edges of two or more parallel or nearly parallel members




# Some Different Edge Shapes and Symbols for Edge Joints



# Proper terminology is needed in everyday job communication


- *Q Joint design* identifies, "the shape, dimensions, and configuration of the joint
- **A The individual workpieces of a joint are called** *members*.
- **A Three types members nonbutting member, butting member, and splice member**

A butting member is "a joint member that is prevented, by the other member from movement in one direction perpendicular to its thickness dimension"




Anonbutting member is "a joint member that is free to move in any direction perpendicular to its thickness dimension

## A *splice member* is "the work piece that spans the joint in a spliced joint




Single-spliced butt joint



Double-spliced butt joint with joint filler


#### Welding Defects

### UNDERCUT





#### **POROSITY**



#### INCOMPLETE FUSION



#### OVERLAP



#### UNDERFLL





#### SPATTER





### EXCESSIVE CONVEXITY



#### EXCESSIVE CONCAVITY






### EXCESSIVE WELD REINFORCEMENT



#### INCOMPLETE PENETRATION & EXCESSIVE PENETRATION



### UNACCEPTABLE WELD PROFILES



### Welding symbols

#### •Reference Line

Reference Line (Required element)



Always Horizontal

#### **Arrow Line**

Reference Line (Required element)

Arrow



#### Tail

Reference Line (Required element)

Arrow





Reference Line must always be horizontal,

Arrow points to the line or lines on drawing which clearly identify the proposed joint or weld area.



Arrow

#### Tail

The tail of the welding symbol is used to indicate the welding or cutting processes, as well as the welding specification, procedures, or the supplementary information to be used in making the weld.

Reference Line must always be horizontal,

Arrow points to the line or lines on drawing which clearly identify the proposed joint or weld area.

#### Basic components of a WELDING SYMBOL

Reference Line (Required element)

Arrow connects reference line to arrow side member of joint or arrow side of joint

Arrow

Tail omitted when reference not used

The tail of the welding symbol is used to indicate the welding or cutting processes, as well as the welding specification, procedures, or the supplementary information to be used in making the weld.

#### All the way Around

A circle at the tangent of the arrow and the reference line means welding to be all around.



#### Field Weld Symbol

A flag at the tangent of the reference line and arrow means Field Weld.




### **Weld Symbol Terminology**

OTHER SIDE


**ARROW SIDE** 



# Break in arrow means arrow side must be side that beveling or other preparation required.



#### Fillet Weld (Arrow Side Only)



## Fillet Weld (Other Side)



## Size of Fillet Weld Noted

1/4

1/4




#### **Example of Double Bevel Groove weld**

Depth of preparation or groove


1/4 (5/16)

1/4 (5/16)



Depth of penetration

# Plug or Slot Weld Symbol Arrow Side




## Represent?


5/16

5/16




# Single-Bevel-Groove and Double Fillet Weld Symbol







# Chain Intermittent Fillet Weld Weld both sides each end and 10 inches center to center in between



# Staggered Intermittent Fillet Weld

Weld ends than 10 inch centers staggered each side





#### The End



BY: DEEPAK BILLUR (2928)